



Tools Needed: Scissors, Pin, Tape Measure, Masking tape, Credit or Bank card  
Apply to surface when temperature is between 50 and 80 F 10C and 27C. Avoid application in windy conditions. Seek another persons assistance before applying a very large graphic.

1. Clean surface thoroughly. Remove any dirt, grease, residue, etc, using alcohol or acetone (fibreglass or gel coat only).
2. Tape the graphic in the general area to which it will be applied.
3. Measure and adjust location of graphic using the baseline and centreline as references.
4. Tape down the centre once the graphic is measured into place.
5. Lift one side of the graphic and separate the application tape from the backing paper. Using scissors, cut away that half of the backing paper.
6. Hold the application paper away from working surfaces keeping it slightly slack and squeegee outward from the centre. Pull squeegee firmly against surface, hard enough to squeegee out any air from beneath the letters.
7. Discard centre strip of the masking tape and lift remaining side of graphic. Remove the backing paper and squeegee outward from the centre.
8. Squeegee the entire graphic again pressing hard.
9. Remove the application tape by pulling it back on itself, not 90 degrees to the surface.
10. Eliminate any bubbles by pricking the vinyl with a sewing needle or pin and pressing down with a finger or squeegee to expel the air.

